

6

5

4

3

2

1

D

D

C


C

B

B

A

A



NOTE:

Some hardware related modifications on the Developerboard LX might be necessary when connecting a USB port to X17. R113, R114, R112, R115, R116 are all 4k7 ohm and this is too much. Replace these with 0 ohm resistors instead. The pull up resistors R106 and R107 shall be replaced with 4k7 ohm.

This is a prototype construction. Please send your feedback to dev-etrex@axis.com.

Name:	Prod No:	Rev:
USB on Developerboard LX	xxx	R1_3
CIRCUIT DIAGRAM	Date:	Des:
AXIS COMMUNICATIONS AB, SWEDEN	May 22, 2002	MM
	Sheet	Appr:
	1 of 1	